

Crossover older pumps



| 1st Gen. | Part No. | 2nd Gen. | Part No. | 3rd gen. | Part No. | 4th Gen. | Part No. | 5th Gen. | Today's Pumps |
|----------|-----------|----------|-----------|-----------------------|-------------|----------|------------|-----------|--------------------|
| | | | | H125 | 32.01.001U | | | | H40B6-EN |
| | | | | H125CN | 32.01.001CN | | | | H40B6CEV |
| | | | | H250 | 32.01.002U | | | | H120B6-EN |
| | | | | H250CN | 32.01.002CN | | | | H120B6CEV |
| | | | | H375 | 32.01.003U | | | | H120B6-EN |
| | | | | H375CN | 32.01.003CN | | | | H120B6CEV |
| | | | | H500 | 32.01.015U | | | | H240E6-LN |
| | | | | H500CN | 32.01.015CN | | | | H240E6-LV |
| | | | | H125TEFLON | 33.01.001 | | | | H40B6CEV |
| | | | | H250TEFLON | 33.01.002 | | | | H120B6CEV |
| | | | | H375TEFLON | 33.01.003 | | | | H120B6CEV |
| | | | | H500TEFLON | 33.01.004 | | | | H240E6-LV |
| | | | | H1000 | 32.01.016 | | | | H240E6-LN |
| | | | | H2000 | 32.01.017 | | | | (2) H240E6-LN |
| | | | | H4000 | 32.01.018 | | | | (4) H240E6-LN |
| | | | | L15X1 | 32.01.037 | | | | L7A6-BN |
| | | | | L15X1 (1/8" vac port) | 32.01.058 | L5 | 32.01.080 | | L7A6-AN |
| | | | | L15X2 | 32.01.038 | | | | L7A6-CN |
| | | | | L30X1-32.01.040 | 32.01.040 | L10 | 32.01.081 | | L14A6-BN |
| | | | | L30X1 (1/8" vac port) | 32.01.059 | L10 | 32.70.081B | | L14A6-AN |
| | | | | L30X2 | 32.01.041 | | | | L14A6-CN |
| | | | | L45X1 | 32.01.043 | | | | L28A6-BN |
| | | | | L45X2 | 32.01.044 | | | | L28A6-CN |
| | | | | L60X1 | 32.01.046 | L20 | 32.01.076 | | L28A6-BN |
| | | | | L60X2 | 32.01.047 | L20X2 | 32.01.082 | | L28A6-CN |
| | | L63 | 31.01.053 | L63D | 32.01.004 | MLD25 | 32.01.070 | | L25B6-EN |
| | | L125 | 31.01.054 | L125D | 32.01.005 | MLD50 | 32.01.071 | | L50B6-EN |
| | | | | L190D | 32.01.006 | MLD100 | 32.01.072 | | L100B6-EN |
| | | | | L250D | 32.01.007 | MLD100 | 32.01.072 | | L100B6-EN |
| | | L250 | 31.01.065 | | | | | | L100B6-EN |
| | | L500 | 31.01.066 | | | | | | MLL200 |
| | | L1000 | 31.01.067 | | | | | | MLL400 |
| | | L2000 | 31.01.068 | | | | | | MLL800 |
| | | L4000 | 31.01.069 | | | | | | MLL1200 |
| | | | | | | LX5 | 32.01.051 | | X5A5-AN |
| | | | | | | LX10 | 32.01.078 | | X10A5-AN |
| | | M16 | 31.01.042 | | | X5 | 32.01.083 | | M5A5-AN |
| | | M32 | 31.01.043 | | | X10 | 32.01.084 | | M10A5-AN |
| | | M60 | 31.01.089 | | | X10 | 32.01.084 | | M20A5-BN |
| M63 | 31.01.001 | M63 | 31.01.093 | M63D | 32.01.009 | MLD25 | 32.01.070 | | M25B5-EN |
| M63 | 31.01.033 | M63 | 31.01.093 | M63D | 32.01.009 | MLD25 | 32.01.070 | | M25B5-EN |
| | | | | | | MLD25ES | 32.01.087 | | M25B5-ENAF |
| M125 | 31.01.003 | M125 | 31.01.094 | M125D | 32.01.010 | MLD50 | 32.01.071 | | M50B5-EN |
| M125 | 31.01.034 | M125 | 31.01.094 | M125D | 32.01.010 | MLD50 | 32.01.071 | | M50B5-EN |
| | | | | | | MLD50ES | 32.01.088 | | M50B5-ENAF |
| | | | | M190D | 32.01.011 | MLD100 | 32.01.072 | | M100B5-EN |
| M250A | 31.01.035 | M250B | 31.01.095 | M250D | 32.01.012 | MLD100 | 32.01.072 | | M100B5-EN |
| | | | | | | MLD100ES | 32.01.089 | | M100B5-ENAF |
| | | | | M375D | 32.01.013 | MLD100 | 32.01.072 | | M100B5-EN |
| | | M250 | 31.01.010 | | | MLD100 | 32.01.072 | | M100B5-EN |
| | | M500 | 31.01.015 | | | MLL200 | 31.01.056U | | MLL200 |
| | | M1000 | 31.01.037 | | | MLL400 | 31.01.057U | | MLL400 |
| | | M2000 | 31.01.030 | | | MLL800 | 31.01.058U | | MLL800 |
| | | M4000 | 31.01.040 | | | MLL1200 | 31.01.059U | | MLL1200 |
| | | | | | | X5 | 32.01.083 | | X5A5-AN |
| | | | | | | X10 | 32.01.084 | | X10A5-AN |
| | | | | | | XLC20 | 33.01.042 | | X20F5-TN |
| | | | | | | XLC20ES | 33.01.045 | | X20F5-TN/01.03.110 |
| | | | | | | XLC40 | 33.01.043 | | X40F5-KN |
| | | | | | | XLC40ES | 33.01.046 | | X40F5-KN/01.03.110 |
| | | | | | | XLC60 | 33.01.044 | | X50F5-KN |
| | | | | | | XLC60ES | 33.01.047 | | X50F5-KN/01.03.110 |
| | | | | | | XLD100 | 33.01.010 | | X120B6-EN |
| | | | | | | XLD100ES | 33.01.031 | | X120B6-ENAF |
| | | | | | | XLD200 | 33.01.020 | | X240E6-LN |
| | | | | | | XLD200ES | 33.01.032 | | X240E6-LN/ES25/1 |
| | | | | | | XLD300 | 33.01.030 | | X320E6-LN |
| | | | | | | XLD300ES | 33.01.033 | | X320E6-LN/ES25/1 |
| | | | | | | XED150 | 33.01.040 | | XED150 |
| | | | | | | XEDH150 | 33.01.039 | | XEDH150 |
| | | | | | | | | M150E6-LN | M150B5-VN |
| | | | | | | | | M200E6-LN | M200B5-VN |
| | | | | | | | | X160E6-LN | |
| | | | | | | | | X240E6-LN | |
| | | | | | | | | X320E6-LN | |
| | | | | | | | | H240E6-LN | H240B6-VN |